

AUTHORIZATION NEEDED TO OBTAIN NEGATIVE LENSES IN THE OPTICAL

SYSTEM® S PERISCOPE HAS NOT BEEN FORTHCOMING.

ASSUMED THAT

THIS HAD BEEN INITIATED WHEN CORRECTIVE ACTION WAS REQUIRED IN

ARTICLE 124. TELEPHONE CONVERSATION WITH

ADVISES

THAT HE HAS ORDERED FIVE LENS WHICH ARE TO BE PLACED IN FORTH—

COMING UNITS. HOWEVER, NO LENSES HAVE BEEN ORDERED FOR EQUIP—

MENT SHIPPED FROM FACTORY AS OF THIS DATE, ALL OF WHICH WILL

REQUIRE RETROFIT. REQUIREMENT EXISTS FOR TWELVE NEGATIVE LENS

IN ADDITION TO THOSE ALREADY ON ORDER. SERIOUS VIEWING PROBLEMS

ARE EXPECTED UNTIL THE SITUATION IS REMEDIED. ADVISE.

25X1A

INSTALLED (25-127)-NB

SECRET

CROUP I Maded from enformatic downgrading and eaclessification 25X1A